

Map ID
Direction
Distance
Elevation

MAP FINDINGS

EDR ID Number
EPA ID Number

FS857
North
> 1
1.164 mi.
6146 ft.

COSTELLA HOME
2060 WEST 11TH STREET
BROOKLYN, NY

NY Spills S108296639
N/A

Site 1 of 2 in cluster FS

Relative:
Higher

Actual:
14 ft.

SPILLS:

Name: COSTELLA HOME
Address: 2060 WEST 11TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0610244 / 2006-12-20
Facility ID: 0610244
Facility Type: ER
DER Facility ID: 324311
Site ID: 374644
DEC Region: 2
Spill Cause: Other
Spill Class: C4
SWIS: 2401
Spill Date: 2006-12-08
Investigator: rvketani
Referred To: Not reported
Reported to Dept: 2006-12-08
CID: 444
Water Affected: Not reported
Spill Source: Private Dwelling
Spill Notifier: Other
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2006-12-08
Spill Record Last Update: 2006-12-20
Spiller Name: MRS COSTELLA
Spiller Company: COSTELLA HOME
Spiller Address: 2060 WEST 11TH STREET
Spiller Company: 001
Contact Name: MRS COSTELLA

DEC Memo:

"Spilled outside through vent line In cellar- oil on floor under tanks. Setup is 2- 275 gal tanks attached with piping at the bottom. Leak is from the bottom of one tank at the joint with pipes. Approx 5 gal on basement floor. Cleanup/repairs being made. Need to followup that cleanup/repairs are complete. 12/19/06 - Raphael Ketani. The spill happened on 12/8/06. Number 2 oil came out the vent pipe as an overfill. Madison Oil (718) 444-3400 (Rich Turchiano) responded and also found that 5 gals. had leaked out onto the basement floor from the tank where a pipe was connected. The homeowner is Mrs. Costella at (718) 256-9181. I spoke to Mr. Turchiano and asked him for any copies of paid bills. He said that he just had the ticket for the repair work. He said that Fleet Transportation had delivered the oil for Madison and they had overseen the repair and cleanup. He said the number was (347) 219-7697 and the contact was Mike. I told him to send me a copy of the ticket anyway. He said he would. I spoke to Mrs. Costella. She said that everything was repaired and cleaned up quickly. She said the odors were bad before, but now they are much less. She said she doesn't smell the odors in the first floor apartment, but only the basement. She said she doesn't have any bills or receipts for the work that was done. She told me to call Fleet or

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

Remarks:

Madison. I spoke to Mike of Fleet. He said that he thought there were some receipts or tickets for the repair and cleanup work done. He said he will look for them and FAX them - if he finds them. 12/20/06 - Raphael Ketani. I received a FAXed service invoice from Mr. Turchiano. It shows that a bag of absorbent was used, copper tubing was replaced along with some fittings and a ball valve. As there is no other documentation available regarding the cleanup of the spill, and since the spill was only 5 gals., and as Mrs. Costella told me the spill was cleaned up and the odors are less, I am closing the spill case. "

"OWNER ORDER TOO MUCH OIL AND IT DID NOT NEED IT AND SOME SPILLED OUT LESS THEN 1/2 GALLON AND IS BEING CLEANED UP: Update at 15:08 - found 5 gallon spill in basement and our cleaning it up; spill from nipple pipe which had rotted;"

All Materials:

Site ID: 374644
Operable Unit ID: 1132309
Operable Unit: 01
Material ID: 2122048
Material Code: 0001A
Material Name: #2 fuel oil
Case No.: Not reported
Material FA: Petroleum
Quantity: .00
Units: G
Recovered: .00
Oxygenate: Not reported